



# ETON America, LLC



## Service Bulletin

<b>Bulletin No:</b> 0006	<b>Oil Tank Bracket Bolts Comes Loose</b>
<b>Date:</b> 07/21/2000	

### Lightning 50 / Thunder 90 (AXL/TXL-50 & 90)

**REASON FOR BULLETIN:**

OIL TANK BOLTS COMING LOOSE AND DROPPING TANK ON ENGINE AND BURNING HOLE IN TANK.

**AFFECTED UNITS:**

ALL AXL-TXL 50 & 90cc MODELS

**REPAIR:**

INSTALL LOCK TIGHT TO ALL 3 OIL TANK BOLTS FOLLOW STEPS BELOW

STEP 1: REMOVE THREE OIL TANK MOUNT BOLTS.

STEP 2: APPLY A QUALITY LOCK TIGHT TO ALL THREE OIL TANK MOUNT BOLTS. TIGHTEN THREE BOLTS. (A HIGH TEMP STYLE IS RECOMMENDED)

STEP 3: ROAD TEST AND RE-TIGHTEN BOLTS IF NECESSARY.