



ETON America, LLC



Service Bulletin

Bulletin No: 0032

Date: 07/23/2004

2005 Viper Models No Power

Viper models with no power or bad throttle response. Remove the 4mm spark arrestor retainer bolt as shown in figure 2. Then remove the spark arrestor with a pair of needle nose pliers (figure 3). Then clean the screen or replace the element part # 811008.

Symptoms of a dirty spark arrestor.

1. Loss of power or no power
2. Bad throttle response
3. No start situation



Figure 1



Figure 2



Figure 3



Figure 4