



ETON America, LLC



Service Bulletin

Bulletin No: 0010
Date: 09/11/2000

Ground bolt replacement for Yukon 150

Yukon 150 (YXL-150)

UNITS AFFECTED:

ALL YXL-150 UNITS BUILT BEFORE SEPT. 2000
(VIN Prior to **RFZFJA0Sx0A001501**)

REASON FOR BULLETIN:

POOR GROUND AT REGULATOR

REPAIR:

REPLACE GROUND BOLT AT REGULATOR, (ONLY for Models that have grounding wire on the Regulator)

1. Remove grounding bolt, (see picture), clean contact surface on regulator and ground wire lead with sand paper. Replace grounding with a non-coated (M6 X 20) bolt & washer.
Test for good ground.

