



## Service Bulletin

Bulletin No.: **SB-0061**

Date: 08/23/2010

## Carburetor Float Adjustment 90cc 4-Stroke Models

### Models Affected: Viper 90R-4S, Rover UK-1, Rover GT

Use the following guide for adjusting the carburetor float on E-TON 4-stroke carburetors (part numbers 811613 and 812466).

When fully extended (as shown in figure 1), make a mental mark of the half-way point on one side of the float. When properly adjusted, this mark should meet with the edge of the carburetor when the float is in its contracted position as shown in figure 2.



**FIGURE 1**

Mark halfway point of float when extended (white line).



**FIGURE 2**

Correctly-adjusted float should have the halfway point meet the edge of the carburetor as shown by the white mark when contracted.