



Service Bulletin

Bulletin No: 0014	Rascal (IXL 40): CDI Speed Limiter Adjustment Procedure.
Date: 03/07/2001	

Rascal IXL 40 CDI Speed Limiter Adjustment Procedure

Units affected:

All IXL-40 models (Rascal).

Reason for bulletin:

CDI speed limiter adjustments.

Repair:

Adjusting CDI speed limiter as required

Verify repair:

Road test and verify ease of starting and proper speed range after speed limiter is adjusted.

Rascal CDI Speed Limiter Adjustment

Adjusting the CDI speed limiter will also reduce plug fouling concerns and is a more efficient way to adjust speed for beginning riders. Adjust the CDI speed limiter to the desired speed and power and then adjust the throttle stop screw for restricting amount of throttle available. The following pictures show where the CDI speed limiter adjustment screw is located. Remove rubber cover for access to screw. Speed adjustment on the CDI is done by turning the white screw in the adjustment pod.

To **decrease** the speed turn the
To **increase** the speed turn the



adjustment screw **clockwise**.
adjustment screw **counter-clockwise**.