



ETON America, LLC



Service Bulletin

Bulletin No: 0058
Date: 09/22/2008

**Matrix R4-150, Beamer R4-150, YXL-150,
CXL-150 hard starting, long startup time.**

PROBLEM: Bikes are hard to start when cold, and when started it takes a long time before you can give any throttle.

SOLUTION: Remove the carburetor, remove the screws from the bowl. Replace the stock pilot jet #35 with a #38 pilot jet (Part #810423). This will improve your startup and warm-up time on a cold bike.

