



# ETON America, LLC




## Service Bulletin


Bulletin No.: **SB-0059**

Date: 06/01/2009

## E-TON 40cc Carburetor update



Old style Carburetor **does not** require replacing the inlet pipe.



NEW style Carburetor **DOES** require replacing the inlet pipe.



700130

The New Designed carburetor supplied on engine numbers ending with 010772 and greater.

Engine numbers ending with a number lower than 010772 **REQUIRE** Replacing this part before installing the new style carburetor.