



ETON America, LLC



Service Bulletin

Bulletin No:	0017
Date:	03/07/2001

Rascal (IXL 40): Fuel/oil Mixture Ratio Update

Rascal IXL 40

Oil Mixture Update

Units affected:

All IXL-40 models (Rascal).

Reason for bulletin:

Update Fuel/oil mixture ratio

Repair:

Change fuel/oil mixture to 50:1

Verify repair:

Road test and verify ease of starting

Rascal IXL 40 Oil Mixture

After an extensive amount of research into the proper fuel/oil mixture for the Rascal IXL-40 we have determined the proper fuel/oil mixture ratio to be 50:1.

Our research showed that with today's oil technologies a mixture of 50:1 is perfectly acceptable and this change will reduce plug fouling concerns and aid in easier starts.

We recommend a high quality pre-mix oil such as BELL-RAY, Golden Spectro etc.

Rascal IXL-40 Fuel / Oil Ratio 50:1 2 1/2oz of oil per 1 gallon 89 Octane fuel