



ETON America, LLC



Service Bulletin

Bulletin No: 0020
Date: 8/19/03

Wire Routing For Brake/Tail Lights

The rear tail light wires may have been routed where they are caught between seat supports and frame. This could cause a short in the harness or tail lights shown in figure 1. They should be routed behind the battery and pulled up through the plastic to connect to the rear tail lights as shown in Figure 2.

Figure 1



Figure 2

